




IDTech OPOS MSR Test Guide

H/W Dept / Luke Kim


2025-08-11

OPOS MSR TEST Guide


MSR TEST




- Connect MSR to POS
- Run SecureMag_USB_Demo Program



- Click General Setting




- Select USB HID Mode




- Check Message.(SecureMag USB HID Reader Connected)
- Slide Card and Check Data(Like yellow area)

OPOS MSR TEST Guide

OPOS Open




- Run MSR OPOS Test Program.




- Click down pointed arrow in Red Circle area

OPOS MSR TEST Guide




- Select mode to IDTECH_SECUREMAG_USBHID – USB HID.



- Click Open

OPOS MSR TEST Guide



- Check Open Succeeded! Message